## Emeryville Senior Center Change Order Log 10 07 16

PCO No.	Description			Amount			
Differing Site Conditions							
1	Additional flooring removal		\$	4,057.87			
2.1	Ridge Framing		\$	1,466.92			
3.2	Bar area ceiling tiles			5,082.46			
12	HD5 hold downs		\$ \$ \$ \$	559.99			
13	Additional abatement		\$	22,123.28			
15	Additional PV supports		\$	13,918.60			
17	Roof 2 rafter		\$	708.94			
18	Roof 4 joist			1,206.39			
19	Roof 2 blocking		\$ \$	3,147.92			
21	Southwest roof structural		\$	7,049.11			
24	Unisex restroom plumbing line routing changes		\$	8,872.41			
28.1	Roof 4 structural work		\$	15,445.15			
32.1	Entry stair concrete work		\$	7,000.89			
33	Hydronic piping		\$	17,090.58			
36.1	PV support flashing		\$ \$ \$	8,265.89			
38.1	First floor office abatement		Ś	4,910.77			
43	Single panel door add		\$	1,810.78			
46	Unisex floor underlayment		\$	2,056.06			
50	Ramp foundation conflict and electrical wiring		\$	3,944.57			
56	Window furring		\$	5,691.48			
62	Washer Dryer model change		\$	424.82			
85	Office floor underlyament		\$	2,289.48			
87	Bench Fabrics			852.55			
88c	Weather and schedule extension		\$ \$	59,308.60			
91	Brick cutting		\$	4,739.41			
31	Short cutting	Total:		202,024.92			
Deferred	Building Maintenance Upgrades						
4.1	Gravity Exhaust Fans		\$	5,091.51			
5.1	Insta Hot			1,608.39			
6	Flag pole		\$ \$	4,544.28			
9	Additional electrical work			1,428.49			
11	Dry rot damage		\$ \$ \$ \$	1,177.67			
23	Roof scupper coring and relocation		\$	6,067.57			
25	Fire Alarm panel outlet		\$	1,902.69			
26B	Glass block replacement		\$	4,695.58			
29	Flag pole lighting			4,860.52			
31	Existing water damage		\$	6,443.43			
35.1	Storage room 4 new door and hardware		\$	3,542.58			
37	Mens restroom tiles		\$ \$ \$ \$	2,823.63			
41	Flagpole base		\$	893.18			
47	Video mens restroom sewer line		\$	525.24			
49	Lowering the water main and leak repair at meter			6,766.11			
53.1	Scuppers & downspouts		\$ \$	17,198.34			
58	Bath Partitions		\$	1,441.56			

## Emeryville Senior Center Change Order Log 10 07 16

PCO No.	Description			Amount
61	Data demo and patch repair		\$	1,594.98
67	Quarter round and nosing			1,717.50
71	MP room flooring repair		\$ \$	2,856.44
80	Exterior crack sealing		\$	1,109.03
		Total:	\$	78,288.72
City Requ	uest			
8.1	Sidewalk replacement		\$	12,428.02
14.2	Added Data work		\$	39,845.91
30.2	Retrofit multipurpose room chandeliers		\$	7,434.56
39	Carpet in Brad's office and Billard room		\$	11,185.06
63	Additional MP room painting		\$ \$ \$ \$	1,808.42
74	Window film		\$	935.41
75.1	Blinds			5,978.14
81.1	Chairs relocation		\$ \$ \$ \$	630.50
82	Pump alarm conduit		\$	2,190.53
83.2	Concrete and brick work on front steps		\$	12,092.72
86	Added interior signs		\$	895.63
89.1	Replace tile with wood base in main lobby		\$	5,433.50
90	VCT rear hall		\$	248.47
93	Brick/sand landscape area on side of curb ramp		\$	2,993.55
		Total:	\$	104,100.42
Design R	elated			
16	Added door hardware		\$	8,374.18
20	Single pipe penetrations		\$	2,999.55
27	Multipurpose room lighting changes		\$ \$ \$ \$ \$	24,082.39
40.1	Roof 4 MEPs		\$	19,005.42
54	Trash enclosure additional panel		\$	1,444.50
59	Door hardware credit		\$	(7,965.08)
66	Wood Moulding		\$	4,184.16
103	Roof 4 work for warranty		\$	8,404.52
		Total:	\$	60,529.64
Fire/Buil	ding Inspector Identified Code Upgrades and Regulato	rv Comr	oliance	
10.4	Sewer line replacement/Underground tank removal	.,	\$	42,634.46
34	Sewer lateral video		\$	860.51
45	Reline sewer		Ś	8,122.34
51.2	Additional tank removal costs		Ś	15,000.00
52.2	Soil Analysis during tank work		\$	2,461.30
55	Plumbing bracing		\$	404.70
68	Soil disposal		\$ \$ \$ \$ \$	9,839.94
69	Fire Alarm drawings		, \$	11,125.92
70	Sewer lower lateral test			1,873.38
72	Trench backfill		\$ \$	6,297.17
73.1	North storm drain and sump pump discharge work		\$	18,603.30
76	South storm drain		\$ \$	11,220.84
77	ADA curb ramp and revised sidewalk layout		\$	12,311.07
	stanp and remode side training out		Ŧ	12,311.07

## Emeryville Senior Center Change Order Log 10 07 16

PCO No.	Description			Amount		
78	Excess soil disposal		\$	12,397.03		
79.1	BAR room gyp board		\$	7,515.82		
84	FA work		\$	8,174.71		
92	Add fire alarm power panel		\$	719.88		
98	New smoke detector		\$	4,867.47		
99	Temp ramp sidewalls		\$	2,849.00		
		Total:	\$	177,278.84		
Miscellaneous scope deduct credits						
44	Duct work credit		\$	(1,873.65)		
48	Drinking Fountain credit		\$	(3,689.21)		
57	Aocustic Panel credit		\$	(7,896.63)		
60	Soil Waste Line credit		\$	(2,685.21)		
		Total:	\$	(16,144.70)		
		Total of all above :	\$	606,077.84		